

PHASE CHART

	1	2	3	4	5	6	7	8	9	10	11	12	
Phase 1 + 5			R			R	R	R	R	R	R	R	
1 & 5 Change	THE CONTROLLER MAY SKIP TO PHASES 1 + 6 OR 2 + 5 OR 2 + 6												
Phase 1 + 6			G	R	R	G	R	R	R	R	R	R	
1 + 6 Change			Y	R	R	G	R	R	R	R	R	R	
Phase 2+5	R	R	R			R	R	R	R	R	R	R	
2 + 5 Change	R	R	R			R	R	R	R	R	R	R	
Phase 2 + 6	G	G	G	G	G	G	R	R	R	R	R	R	
2 + 6 Change	Y	Y	Y	Y	Y	Y			G	R	R	R	
Phase 3	R	R	R	R	R	R			G	R	R	R	
3 Change	R	R	R	R	R	R	Y	Y	Y	R	R	R	
Phase 4	R	R	R	R	R	R	R	R	R			G	
4 Change	R	R	R	R	R	R	R	R	R	Y	Y	Y	
Fashing Operation	FL/Y	FL/Y	FL/Y	FL/Y	FL/Y	FL/Y	FL/Y	FL/Y	FL/R	FL/R	FL/R	FL/R	

WIRING KEY

